


FIG. 1






FIG. 2




FIG. 3






FIG. 4



**FIG. 5**

**Panel A**

TO1380-140944620



**FIG. 5**


**Panel B**

09944604 . 083104



**FIG. 6**

FIG. 7







FIG. 8



**FIG. 9**


01033101 4496400-00000000

101380-4546560




**FIG. 10**

TOTE80 "through660




**FIG. 11**

0103308349490



**FIG. 12**

FIG. 13



After 4 washes

After 8 washes





FIG. 14

FIG. 15



## TOTE 310 " Height

				1	Ti Survey
1	XTRA AMP	$10^3$	4.2	1	$10^3$
2	2	1	4.3	1	1
3	3	1	4	1	$10^2$
4	4	$10^2$	4.4	1	1
5	5	1	4.5	1	$10^1$
6	6	$10^1$	1.6	1	1
7	7	1	0.7	1	$2 \times 10^0$
8	8	$2 \times 10^0$	0.8	1	1
9	9	1	0.9	1	1
10	.	.	10	.	.
11	.	.	.	11	FILTER/Ti Survey
12	NC-XA	4.12	1	1	$10^3$
13	.	4.13	1	1	1
14	NC-TI	0.14	1	1	$10^2$
15	.	2.15	1	1	1
16	NC-F	0.16	1	1	$10^1$
17	.	2.17	1	1	1
18	*Note: All Signals Read at 20 minutes.	2.18	1	1	$2 \times 10^0$
19	.	0.19	1	1	1

FIG. 16




FIG. 17




FIGURE 18



FIGURE 19




FIGURE 20



FIGURE 21



FIGURE 22




FIGURE 23



FIGURE 24



FIGURE 25




FIGURE 26